Index No. V3

# CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____

N1/4 31 Corner common to sections 30, 31




## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1875

Original monument Post

Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | Sugar | Ash | | |
| Diameter | 4" | 6" | | |
| Bearing | S50E | S29E | | |
| Distance | 290 LKS | 261 LKS | | |

### Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1930 By GLO

Location filed Sec. of State

Monument Set 1436" Id. w/brass cap 1/4 S30
1/4 S31
1930

Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | Elm | Poplar | | |
| Diameter | 8" | 8" | | |
| Bearing | N15E | S32½E | | |
| Distance | 25 LKS | 36 LKS | | |

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - Gary Stevenson - 1982
Doc. # 264960
Found GLO monument in good condition
7" Ash N71W 15.13';
5" W. Oak S10W 34.86';
4" W. Oak N20E 17.42'

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____