


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
E 1/4 31 Corner common to sections 31, 32



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Aspen</u>	<u>Balsam</u>
Diameter	<u>8"</u>	<u>4"</u>
Bearing	<u>N 5° E</u>	<u>N 72° W</u>
Distance	<u>30 links</u>	<u>28 links</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 6/1930 By H.D. Craig, US Surveyor
Location filed: Minn. Hist. Society, notes
Monument: Set 1"x 36" iron pipe with brass cap at lost position and marked new witnesses as follow. 1/4 S31| S32 1930

Evidence of Subsequent Corner Restoration

Year of search 1968 By L. Martinson, USFS
Location filed: USFS Book 2, page 3, 5680-11
Monument: Found iron and brass cap and witness as follow.

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>Poplar</u>
Diameter	<u>6"</u>	<u>12"</u>
Bearing	<u>N 40 1/2° E</u>	<u>S 68° W</u>
Distance	<u>12 links</u>	<u>64 links</u>

Bearing Trees, Reference Objects

Species	<u>Birch</u>	_____
Diameter	<u>6"(1930)</u>	_____
Bearing	<u>N 41° E</u>	_____
Distance	<u>12 links</u>	_____

Subsequent Corner Restoration

Year surveyed 3/1981 By G. Brama, USFS
Location filed: USFS Book 2, page 3
Monument: Found iron pipe up 6" and witnesses as follows.
12" Birch, N 41° E, 7.9'(1930) marked BT
11" Red Oak, N 65° E, 49.79' scribed 1/4 S32 BT
12" Elm, S 60° W, 114.30' scribed 1/4 S 31 BT
15" White Oak, N 89° W, 173.22' scribed 1/4 S31 BT
8" Birch, N 53° E, 4.0' FSLP
Steel Sign Post, North, 4.0'
Steel Sign Post, South, 3.9'


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. X 5

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 31 Corner common to sections 31, 32



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Aspen Balsam
Diameter 8" 4"
Bearing N 5 E N 72 W
Distance 30 LKS 28 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1930 By GLD
Location filed Sec. of State
Monument Set 1x36" 1/4 W/Dress cap
1/4
S31/S32
1930

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Birch Poplar
Diameter 6" 12"
Bearing N 40 1/2 E S 60 W
Distance 12 LKS 64 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Gary Stevenson - 1982
Doc. # 264967
Found GLD monument in good condition
15" W. Oak N 89 W 173.25';
12" Elm S 60 W 114.30';
12" Birch N 41 E 7.9' (1930 BT);
11" Burr Oak N 65 E 49.79'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____