


Index No. X-Y 15

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

W.C. TO Corner common to sections 34

SML ON N-S 1/4 LINE



EXISTING SURVEYS

Original Government Survey

Year surveyed 1930

Original monument 1x36" 1/4" 1/4" 1/4" 1/4" 1/4" 1/4" 1/4"

WC  
C  
5134  
C  
SML  
1930

Bearing Trees

Species Cedar Cedar \_\_\_\_\_  
 Diameter 6" 5" \_\_\_\_\_  
 Bearing N45 1/4 E S69 3/4 W \_\_\_\_\_  
 Distance 37 LKS 66 LKS \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

CERTIFICATE - Gary Stevenson - 1982

Doc. # 264970

Found GLO monument in good condition

5" Cedar N44W 59.60';

5" Cedar North 54.41';

8" Twin W. Oak S65W 31.70'

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_