


Index No. Y.0-03.0

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

C.S. 1/16 Corner common to sections 31



EXISTING SURVEYS

Original Government Survey

Year surveyed 6/1930, H.D. Craig, US Surveyor $S_c \frac{1}{16}$
 Original monument Set 1"x 36" iron pipe w/brass cap $S \left| \begin{matrix} 31 \\ c \end{matrix} \right.$
 1930

Original Evidence Found

Year of search _____ by _____
 Monument found _____

Bearing Trees

Species	<u>Elm</u>	<u>Maple</u>	_____	_____
Diameter	<u>6"</u>	<u>6"</u>	_____	_____
Bearing	<u>N 50° E</u>	<u>S 17° E</u>	_____	_____
Distance	<u>12 links</u>	<u>16 links</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1/1964 By J. Ekstrom, USFS
 Location filed: USFS Book 1, page 1
 Monument: Found GLO corner and the following witnesses.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>Maple</u>	_____	_____
Diameter	<u>6"(1930)</u>	<u>6"(1930)</u>	_____	_____
Bearing	<u>N 50° E</u>	<u>S 17° E</u>	_____	_____
Distance	<u>7.92'</u>	<u>10.56'</u>	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed: _____
 Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

