


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects


Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:



T. 144 R. 31 M. 5TH Coordinates: X Y
N 1/4 9 Corner common to sections 4, 9

EXISTING SURVEYS

Original Government Survey
Year surveyed 1875
Original monument Post

Original Evidence Found
Year of search By
Monument found

Bearing Trees
Species Elm Br. Oak
Diameter 8" 5"
Bearing S 64 W N 80 E
Distance 20 LKS 59 LKS

Original Bearing Trees Found
Species
Diameter
Bearing
Distance

Subsequent Corner Restoration
Year surveyed 1930 By GLO
Location filed Sec. of State
Monument Fnd possible remains of S.W. BIT. and
local stake set at orig position for corner, also fnd
local B.T.: 12" oak stump N 31 3/4 W 103 LKS Set 1K36
1/4" brass cap

Evidence of Subsequent Corner Restoration
Year of search 1979 By HWY DEPT
SPK IN TREATED POST, DOWN 2"
10" POPLAR N 31.4'
4" POPLAR NW 11.3

Bearing Trees, Reference Objects 1930
Species Poplar Oak Fence cor.
Diameter 4" 12" S & E
Bearing S 1/2 E N 71 W S 2 E
Distance 3 LKS 104 1/2 LKS 48 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed By
Location filed
Monument

Evidence of Subsequent Corner Restoration Found
Year of search By