


T. 144 R. 31 M. 5th Coordinates: X _____ Y _____

NE 12 Corner common to sections 11, 12 and 6, 7-144-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search 1930 by Craig
Monument found _____
Resurvey notes page 28

Bearing Trees

Species	Tamarack	Tamarack	White Pine	Tamarack
Diameter	6"	3"	20"	6"
Bearing	S 53° E	S 75° E	N 82° E	N 85° W
Distance	105 links	116 links	219 links	380 links

Original Bearing Trees Found

Species	W. Pine stump	Old stump	Tam. stump	Tanarack
Diameter	24"	root	rotted	stump
Bearing	N 83° E	S 53° E	S 75° E	N 85 1/4° W
Distance	219 links	105 links	120 links	387 links

Subsequent Corner Restoration

Year surveyed 4/1930 By H.D. Craig, U.S. Surveyor, GLO
Location filed: MN Hist. Soc., 144-30 notes pg 27 T144N
Monument: Set 2"x 3' iron pipe. w/brass cap R31W | R30W
from original witnesses, up 10", in SE side S 1 | S 6
of open swamp and new witnessed as S12 | S 7
follows. 1930

Evidence of Subsequent Corner Restoration

Year of search 5/1934 By J.A. Gjelhaug, Eng. CCC
Location filed: USFS Form 874-9
Monument: Found Brass capped 2" Iron pipe
an lists witnesses ad follows.

Bearing Trees, Reference Objects

Species	Birch	Birch	Tamarack
Diameter	5"	12"	6"
Bearing	N 78° E	S 47 1/2° E	S 82 1/2° W
Distance	145 links	108 links	325 links

Bearing Trees, Reference Objects

Species	Birch	Birch
Diameter	8"	6"
Bearing	S 48° E	N 77 1/2° E
Distance	107 1/2 links	145 links

Subsequent Corner Restoration

Year surveyed 1/1986 By C.R. Krause, USFS
Location filed: USFS Field Book 1, page 47
Monument: Found GLO 2" iron pipe with brass cap
up 4", 65' W. of edge of swamp, blazed line to E. and
witnesses as follows.
9" Birch, N 78° E, 95.7'(1930)
11" Tamarack, S 82° W, 214.5'(1930)
7" White Oak, N 71° E, 115.30' spike
15" White Oak, S 77° E, 97.30' spike
15" White Oak, S 41° E, 127.30' spike
12" Birch, N 88° W, 700' FSLP, E. side of N-S Rd.


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. E 25

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 12 Corner common to sections 1, 12 and 6, 7-144-30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>Tam</u>	<u>Tam</u>	<u>W. Pine</u>	<u>Tam</u>
<u>6"</u>	<u>3"</u>	<u>20"</u>	<u>6"</u>
<u>S53E</u>	<u>S75E</u>	<u>N82E</u>	<u>N85W</u>
<u>105LKS</u>	<u>116LKS</u>	<u>219LKS</u>	<u>380LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec. of State
Monument Find Stumps of all 4 B.T.S. Set 2x36" 1/4" W/brass cap T144N
Corner at S.E. side of open swamp R31W R30W

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Trees	Distance
<u>Birch</u>	<u>Birch</u>	<u>Tam</u>	
<u>5"</u>	<u>12"</u>	<u>6"</u>	
<u>N78E</u>	<u>S47 1/2 E</u>	<u>S82 1/2 W</u>	
<u>145LKS</u>	<u>108LKS</u>	<u>325LKS</u>	

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____