

T. 144 R. 31 M. 5th Coordinates: X _____ Y _____
MC #14 Corner common to sections 11, 12



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search 1921 by Horst
Monument found _____
Survey Rec #461, Bk C, pg 431

Bearing Trees

Species White Birch Norway Pine
Diameter 5" 14"
Bearing S 4° W N 12° E
Distance 100 links 70 links

Original Bearing Trees Found

Species Norway Pine
Diameter _____
Bearing N 12° E
Distance 70 links

Subsequent Corner Restoration

Year surveyed 3/1921 By E.B. Horst, LS 376
Location filed: Survey Record #461, Book C, page 431 and Curo Monument: Set 3/4"x 3' I.M. Curo Book 68, image 199, from U.S. BT standing green and plainly marked.

Evidence of Subsequent Corner Restoration

Year of search 10/1930 By H.D. Craig, U.S. Surveyor, GLO
Location filed: MN Historical Society, notes page 42 MC
Monument: Set 1"x 3' iron pipe with brass cap from remains of original bearing trees, up 6" on E. shore of S. Twin Lake and witnessed as follows. S11 | S12
T144N | R31W
1930

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species Norway Pine Birch
Diameter 26"(GLO) 5"
Bearing N 12° E S 4 1/2° W
Distance 70 links 100 links

Subsequent Corner Restoration

Year surveyed 9/1934 By J.A. Gjelhaug, Engineer CCC
Location filed: USFS Form 874-9
Monument: Found brass capped pipe in good condition, up 10" and witness. 20" Norway Pine, N 13° E, 69 1/2 links

Evidence of Subsequent Corner Restoration Found


Year of search _____ By _____
Location filed: _____
Monument: _____

1/1986, C.R. Krause, USFS
Field Book 1, page 57
Found GLO Brass cap pipe, up 4" and 1" galv. I.P. along side, up 16", on the SE shore of Lake Thirteen, 3'+/-, to water, on downslope of bank and witnesses as follows.
Norway Pine, N 12° E, 46.2'(GLO) 4' high stump
12" White Pine, S 1° E, 5.7' 50d spike
12" Norway Pine, N 20° E, 60.2' 50d spike
18" Norway Pine, S 38° E, 47.65' 50d spike

Index No. G-H 21

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X _____ Y _____
MC #14 Corner common to sections 14, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species W. Birch N. Pine
Diameter 5" 14"
Bearing S4W N12E
Distance 100LKS 70LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1921 By E.B. Horst
Location filed COUNTY BOOK "C" P. 431
Monument Two Gout bit: 12" N. Pine N12E 70LKS SET
3 1/4 x 3/8" I.P.
also on micro film - roll 105 BK 68 P. 62

Evidence of Subsequent Corner Restoration

Year of search 1930 By GLO
Find NE BIT. now 26" and second growth birch
S.W. - set 1 x 3/8" I.P. w/ brass cap MC
S11/S12
T144N R 31W
1930

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Birch
5"
S4 1/2 W
100LKS

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____