


Index No. J11

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X _____ Y _____
N14 16 Corner common to sections 9, 16



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Species	Bearing	Trees	Distance
<u>w. Pine</u>	<u>120E</u>	<u>Aspen</u>	
<u>30"</u>	<u>10"</u>		
<u>N20E</u>	<u>S31E</u>		
<u>22 LKS</u>	<u>59 LKS</u>		

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec. of state
Monument Set 1x36" I.P. w/ brass cap 4" below road
Surface 9 LKS S. of G Road
1/4 S9
1/4 S16
1930

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>oak</u>	<u>22"</u>	<u>S143/4W</u>	<u>188 LKS</u>
<u>oak</u>	<u>5"</u>	<u>N37 1/2 W</u>	<u>111 LKS</u>

Evidence of Subsequent Corner Restoration

Year of search 1979 By HWY DEPT
FD 2" CAPPED IRON PIPE, DOWN 0.3'

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>POPLAR</u>	<u>12"</u>	<u>SE</u>	<u>63.7</u>
<u>POPLAR</u>	<u>12"</u>	<u>SW</u>	<u>65.3</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____