



T. 144 R. 31 M. 574 Coordinates: X _____ Y _____
N 14 18 Corner common to sections 718

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
 Original monument Post

Bearing Trees

Species	<u>Aspen</u>	<u>Willow</u>	_____
Diameter	<u>6"</u>	<u>18"</u>	_____
Bearing	<u>SIDE</u>	<u>N 24 W</u>	_____
Distance	<u>128 LKS</u>	<u>65 LKS</u>	_____

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 2/2001 By CCSO
 Location filed CCSO
 Monument Found PK nail on E CR #21
and fence lines N&S. witness
as follows

Bearing Trees, Reference Objects

Species	<u>Twin W. Oak</u>	<u>P. Pole</u>	<u>Twin W. Oak</u>
Diameter	<u>6"</u>	<u>8"</u>	_____
Bearing	<u>N 12° E</u>	<u>S 71° E</u>	<u>S 19° E</u>
Distance	<u>133.00*</u>	<u>147.26*</u>	<u>102.75*</u>

* distance to double head nail

Evidence of Subsequent Corner Restoration

Year of search May 1918 By _____
Top rd order shows no survey

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

J 3

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
