

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. J5

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 574 Coordinates: X 394435.57 Y 279096.38
NE 18 Corner common to sections 7, 8, 17, 18



EXISTING SURVEYS

Original Government Survey
Year surveyed 1875
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees			
Species	<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
Diameter	<u>8"</u>	<u>8"</u>	<u>6"</u>
Bearing	<u>N30W</u>	<u>N38E</u>	<u>S10W</u>
Distance	<u>95 LKS</u>	<u>156 LKS</u>	<u>170 LKS</u>

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration
Year surveyed 1910 By JAMES M. MIDDLETON
Location filed COUNTY BOOK B P. 578
Monument Two Hub Set From Old Govt B.T.S. Burnt B.N. Pine
N30W 95 LKS, STUMP B.N. Pine N38E 156 LKS, B.N. Pine (Down)
S10W 170 LKS, 6"N. Pine SSE 170 LKS AND GO. RAIL SURVEY B.T.S!
16"N. Pine STUMP N57-17W 150.62', 12"N. Pine S49-48W 135.25'

Evidence of Subsequent Corner Restoration
Year of search 1930 By GLO
Find Stumps of NE & NW B.T.S Set 2x36" i.d.
w/ brass cup T144N R31W
57/58
518/517
1930

Bearing Trees, Reference Objects			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects			
<u>N. Pine</u>	<u>J. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
<u>6"</u>	<u>4"</u>	<u>11"</u>	<u>11"</u>
<u>N83 1/2 E</u>	<u>S76 1/2 E</u>	<u>S40 1/2 W</u>	<u>N25W</u>
<u>287 LKS</u>	<u>167 LKS</u>	<u>276 LKS</u>	<u>163 LKS</u>

J5

Subsequent Corner Restoration
Year surveyed 2/2001 By CCSO
Location filed CCSO
Monument Found 2 1/2" steel hexagonal
monument, down 0.2', 3' S. & CR#21
and 4' E. of & CR#143. Add the
following witnesses.

- 13" N. Pine N49°W, 83.50*
- 8" N. Pine S36°W, 98.65*
- 11" N. Pine N48°E, 94.44*
- P. Pole S37°E, 50.77*
- * distance to double head nail

4/2002 file #2002.009 reset mag nail
GPS location.

Evidence of Subsequent Corner Restoration Found
Year of search May 1918 By _____
Trap rd order shows no survey