


Index No. L-M 13

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 57H Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 30 Corner common to sections 15, 16



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1875  
 Original monument Post

**Bearing Trees**  
 Species Aspen Willow  
 Diameter 6" 30"  
 Bearing S87W N53E  
 Distance 138LKS 87LKS

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Subsequent Corner Restoration**  
 Year surveyed 1930 By GLD  
 Location filed Sec. of State  
 Monument End stump of NE bit. Set concrete man.  
2 1/2" long 6" dia. willow cap T144N R31W  
4" below road surface S16 / S15  
nc  
1930

**Bearing Trees, Reference Objects**  
 Species W. Oak W. Oak Mike Leboins log house  
 Diameter 6" 16" 14x16 Ft  
 Bearing N17 1/4 E N84 1/2 W N5 1/4 E  
 Distance 46 LKS 127 LKS 395 LKS

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_