


T. 144 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

S 1/16 13 Corner common to sections 13 and 18-144-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 4/1930, H.D. Craig, U.S. Surveyor, GLO S 1/16

Original monument Set 1"x 3' iron pipe w/brass cap S 13 | S 18

Notes page 14, at proportionate distance and witnessed 1930

Bearing Trees

Species	<u>White Pine</u>	<u>White Pine</u>	_____	_____
Diameter	<u>7"</u>	<u>6"</u>	_____	_____
Bearing	<u>N 17°45' E</u>	<u>S 2°15' W</u>	_____	_____
Distance	<u>38 1/2 links</u>	<u>120 links</u>	_____	_____

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 2/1984 By G. Brama, USFS

Location filed: USFS Field Book 1, page 11

Monument: Found 1" iron pipe with brass cap up 6", 75' S. of woods trail and witnesses as follow.  
White Pine stump, N 18° E, 25.4'(1930) "T" on top of stump  
22" White Pine, S 2° W, 79.2'(1930) hit by lightning  
18" White Oak, S 84° E, 94.50' scribed

Bearing Trees, Reference Objects

Species	<u>White Oak</u>	<u>White Oak</u>	<u>Steel Sign</u>	<u>Steel Sign</u>
Diameter	<u>9"</u>	<u>14"</u>	<u>Post</u>	<u>Post</u>
Bearing	<u>N 64° W</u>	<u>N 17° W</u>	<u>South</u>	<u>West</u>
Distance	<u>63.35'</u>	<u>69.95'</u>	<u>4.0'</u>	<u>4.1'</u>

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed: \_\_\_\_\_

Monument: \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed: \_\_\_\_\_

Monument: \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed: \_\_\_\_\_


Monument: \_\_\_\_\_

Index No. M 25

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

5116 Corner common to sections 13, 18



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1930 5116  
 Original monument 11 3/4" 1 1/2" w/ brass cap 5131518  
1930

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species w. pine w. pine  
 Diameter 7" 6"  
 Bearing N17-45E S2-5W  
 Distance 38 1/2 LKS 120 LKS

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remuneration certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_