


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument: _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument: _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument: _____


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument: _____

Index No. N7

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 20 Corner common to sections 17, 20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Bearing Trees
Species Aspen
Diameter 7"
Bearing S81E
Distance 241LKS
Species Aspen
Diameter 6"
Bearing N86E
Distance 259LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1931 By GLO
Location filed Sec. of state
Monument Set 1x36" l.p. w/brass cap 1/4 517 520 1931

Bearing Trees, Reference Objects

Species J. Pine N. Pine
Diameter 8" 10"
Bearing N57 1/2 E S57 1/2 E
Distance 199LKS 65LKS

Evidence of Subsequent Corner Restoration

Year of search 1925 By Minn. Hwy Dept. 2/11/25 map in Recorder's office - wa Ker to Cass Lake
1" iron pipe & brass cap USGWA 1931 1133.1" w. of C

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

