


Index No. 023

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.N. 116 Corner common to sections 24



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1930  
Original monument 1x36" 11p. willow  
Cup

<sup>C</sup>  
N 116 1/2 S 24  
<sup>C</sup>  
1930

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees		
Species <u>J. Pine</u>	<u>J. Pine</u>	<u>SE. Cor.</u>
Diameter <u>4"</u>	<u>4"</u>	<u>of House</u>
Bearing <u>S 10-45 E</u>	<u>S 41-15 W</u>	<u>N 56-45 W</u>
Distance <u>46 1/2 LKS</u>	<u>43 1/2 LKS</u>	<u>539 LKS</u>

Original Bearing Trees Found		
Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Evidence of Subsequent Corner Restoration.

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_