


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. P17

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 514 Coordinates: X _____ Y _____
E/4 22 Corner common to sections 22, 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875

Original monument Post

Species	Bearing	Trees
<u>W. Pine</u>	<u>N. Pine</u>	
<u>7"</u>	<u>16"</u>	
<u>N77W</u>	<u>S84E</u>	
<u>90LKS</u>	<u>90LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By E. B. Horst

Location filed COUNTY BOOK 'D' P. 67

Monument FIND N. PINE B.T. (Stump)

Evidence of Subsequent Corner Restoration

Year of search 1930 By GLO

Find Stump of SE B.T. Set 1x36" 1/2" witness

Cap

1 1/4

522/523

1930

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Jilpine</u>	<u>10"</u>	<u>NSBE</u>	<u>162 LKS</u>
<u>Jilpine</u>	<u>8"</u>	<u>S80 1/2 W</u>	<u>229 LKS</u>
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____