


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



¼ Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____

Year of search _____ by _____

Original monument _____

Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Certificate of Location of Government Corner filed in Cass County

By _____


Recorders Office as Document _____

Date _____

Index No. P 8

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X _____ Y _____
C.E. 1116 Corner common to sections 20



o = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1931

Original monument 1x36" 1/4" w/ brass cap

C E 1116 C
520
1931

Bearing Trees

Species	<u>Bv. oak</u>	<u>Ash</u>	_____	_____
Diameter	<u>8"</u>	<u>5"</u>	_____	_____
Bearing	<u>N4E</u>	<u>S61 1/2 W</u>	_____	_____
Distance	<u>107 LKS</u>	<u>137 LKS</u>	_____	_____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1940 By Co Hwy Dept

Location filed Co RD in Squaw Point RD file

Monument Brass cap

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Balm</u>	<u>Balm</u>	_____	_____
Diameter	<u>14"</u>	<u>10"</u>	_____	_____
Bearing	<u>NW</u>	<u>NE</u>	_____	_____
Distance	<u>78.0</u>	<u>79.7'</u>	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____