


Index No. Q21

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S116 Corner common to sections 23,24



EXISTING SURVEYS

Original Government Survey	
Year surveyed <u>1930</u>	<u>S116</u>
Original monument <u>1 x 36" 1 1/2" w/ brass</u>	<u>523/524</u>
	<u>C4P 1930</u>

Bearing Trees	
Species <u>Cedar Snag</u>	<u>Cedar</u>
Diameter <u>10"</u>	<u>4"</u>
Bearing <u>N74E</u>	<u>N39-30W</u>
Distance <u>83 LKS</u>	<u>189 LKS</u>

Original Evidence Found	
Year of search _____	By _____
Monument found _____	

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration	
Year surveyed _____	By _____
Location filed _____	
Monument _____	

Bearing Trees, Reference Objects	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Evidence of Subsequent Corner Restoration	
Year of search _____	By _____
_____	
_____	
_____	

Bearing Trees, Reference Objects	
_____	_____
_____	_____
_____	_____
_____	_____

Remuneration certificate prepared \_\_\_\_\_ By \_\_\_\_\_ Date \_\_\_\_\_  
Filed at \_\_\_\_\_

Subsequent Corner Restoration	
Year surveyed _____	By _____
Location filed _____	
Monument _____	

Bearing Trees, Reference Objects	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Evidence of Subsequent Corner Restoration Found	
Year of search _____	By _____
_____	
_____	
_____	