

T. 144 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

NE 26 Corner common to sections 23, 24, 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search 1903 by COE  
Monument found \_\_\_\_\_  
Leech Lake Reservoir

Bearing Trees

Species	Cedar	Cedar	White Birch	Norway Pine
Diameter	6"	4"	4"	16"
Bearing	S 54° W	N 2° E	N 42° W	S 28° E
Distance	16 links	6 links	30 links	66 links

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1903 By H. Dunaway, COE  
Location filed: Leech Lake Reservoir  
Monument:  
Indicates known corner

Evidence of Subsequent Corner Restoration

Year of search 9/1930 By H.D. Craig, U.S. Surveyor, GLO  
Location filed: MN Hist. Soc., notes page 24 T144N R31W  
Monument: Set 2"x 3' iron pipe with brass cap S23 | S24  
from remains of original bearing trees, up 6" S26 | S25  
and notes witnesses as follows. 1930  
12" Cedar, N 17°30' E, 6 links(GLO) badly burned  
20" Norway Pine, S 24°15' E, 66 links(GLO) badly burned

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Cedar	Cedar	Cedar	Cedar
Diameter	14"	5"	5"	8"
Bearing	N 24°15' E	S 71°30' E	S 35°15' W	N 35°30' W
Distance	227 links	60 links	100 links	175 links

Subsequent Corner Restoration

Year surveyed 7/1964 By EKR, DNR  
Location filed: File A64-279 notes  
Monument: Found I.P.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_


11/1970, C.R. Krause, USFS  
USFS Field Book 1, page 25  
Found corner, all 1930 witnesses are fallen, added new witnesses as follows.  
6" Cedar, S 15° E, 33.8' scribed  
7" Cedar, S 28° W, 58.2' scribed  
4" Ash, N 23° E, 9.1' scribed  
8" Ash, S 86° E, 28.3' scribed  
Steel Sign Post, South, 2.0' 54-2 and 54-4 signs

4/1993, W.E. Curo, LS 11395  
Curo Book 332, page 57  
Indicates corner.

Index No. R 21

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 26 Corner common to sections 23, 24, 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees			
Species <u>Cedar</u>	<u>Cedar</u>	<u>W. Birch</u>	<u>N. Pine</u>
Diameter <u>6"</u>	<u>4"</u>	<u>4"</u>	<u>16"</u>
Bearing <u>S54W</u>	<u>N2E</u>	<u>N42W</u>	<u>S28E</u>
Distance <u>16 LKS</u>	<u>6 LKS</u>	<u>30 LKS</u>	<u>66 LKS</u>

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1930 By GLO  
Location filed Sec of State  
Monument End NE, SE & SW BITS - now 12", 20", & 16" and  
N.W. BIT (down) Set 2x36" I.P.W. Brass Cap T144W R31W  
523/524  
526/525

Evidence of Subsequent Corner Restoration

Year of search 1964 By DNR-Engineering  
Map & notes in file  
Found I.P.

Bearing Trees, Reference Objects 1930

Species <u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>
Diameter <u>14"</u>	<u>5"</u>	<u>5"</u>	<u>8"</u>
Bearing <u>N24-15E</u>	<u>S71-30E</u>	<u>S35-15W</u>	<u>N35-36W</u>
Distance <u>227 LKS</u>	<u>60 LKS</u>	<u>100 LKS</u>	<u>175 LKS</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

R-21

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKEMAN - 1970  
Found GLO monument in good condition  
6" Cedar S15E 33.80';  
7" Cedar S28W 58.20';  
4" Ash N23E 9.10';  
8" Ash S86E 28.30'

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_