


Index No. R 7-8

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 35 Corner common to sections 20, 29



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1875  
 Original monument Post

**Bearing Trees**  
 Species Elm Balm of Gilead  
 Diameter 16" 3"  
 Bearing S52 1/2 E N58 E  
 Distance 53 LKS 28 LKS

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Subsequent Corner Restoration**  
 Year surveyed 1931 By GLO  
 Location filed Sec. of State  
 Monument End SE Bot. (down) set w. C.M.C. 60 LKS  
Cast Concrete mon. 24" long 6" dia w/ brass cap  
T144N  
WC 520  
MC 529  
R31W  
1931

**Bearing Trees, Reference Objects**  
 Species Sugar Maple Bc. Oak  
 Diameter 5" 12"  
 Bearing N59 E S44 1/2 E  
 Distance 36 LKS 51 LKS

**Evidence of Subsequent Corner Restoration**  
 Year of search 1925 By Miss. Hwy Dept.  
R/W map in Recorder's office - Walker to Cass  
Lake  
Concrete mon. & brass cap 441.9' w. of G

**Bearing Trees, Reference Objects**

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_