


Index No. R 9-10

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 47 Corner common to sections 21, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	_____	_____
Diameter	<u>4"</u>	<u>4"</u>	_____	_____
Bearing	<u>N 86 E</u>	<u>S 88 1/2 E</u>	_____	_____
Distance	<u>539 LKS</u>	<u>814 LKS</u>	_____	_____

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1931 By GLO  
Location filed Sec. of state  
Monument Set 1x36" IR. w/ brass cap  
T144N  
MC 521  
528  
R31W

Bearing Trees, Reference Objects 931

Species	<u>Tam post 4" dia</u>	_____	_____
Diameter	<u>5' high alongside iron</u>	_____	_____
Bearing	<u>MC 521 ON N. face</u>	_____	_____
Distance	<u>MC 528 ON S. face</u>	_____	_____

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_