


Index No. V21

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X _____ Y _____

NE 35 Corner common to sections 25, 26, 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Species	Bearing Trees			
	Tam	Tam	Tam	Tam
Diameter	<u>8"</u>	<u>6"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>S77W</u>	<u>N39W</u>	<u>N67E</u>	<u>S32E</u>
Distance	<u>17LKS</u>	<u>30LKS</u>	<u>4LKS</u>	<u>24LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1930 By GLO

Location filed Sec. of State

Monument End orig. post's remains of all 4 BITS - Set

Concrete man 24" long 6" dia. w/ brass cap T14N R31W

526/525
535/536
1930

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing Trees, Reference Objects			
	<u>Palms</u>	<u>F. kod</u>	<u>dead Tam</u>	<u>dead tam</u>
Diameter	<u>12"</u>	<u>7"</u>	<u>10"</u>	<u>14"</u>
Bearing	<u>N54-45E</u>	<u>S12E</u>	<u>S21-30W</u>	<u>N48-30W</u>
Distance	<u>30LKS</u>	<u>169LKS</u>	<u>103LKS</u>	<u>403LKS</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____