


Index No. 29

CASS COUNTY LAND CORNER RECORD

T. 145 R. 26 M. 5TH Coordinates: X _____ Y _____
SE 32 Corner common to sections 32, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>Tam</u>	<u>Cedar</u>	
Diameter	<u>15"</u>	<u>6"</u>	
Bearing	<u>N61E</u>	<u>N29E</u>	
Distance	<u>75 LKS</u>	<u>69 LKS</u>	

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEARNS - 1971 - FILED IN 1978
Doc. # 246196
Set 2" x 60" galvanized steel pipe
with brass cap.
9" Tamarack N64W 55.20';
9" Cedar N13W 43.50';
10" Cedar N17E 49.60';
12" Cedar N64E 27.70'

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____