


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. A 5

CASS COUNTY LAND CORNER RECORD

T. 145 R. 27 M. 5TH Coordinates: X _____ Y _____
N 1/4 3 Corner common to sections 3 and 34-146-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Bearing Trees	
Species <u>N. Pine</u>	<u>N. Pine</u>
Diameter <u>8"</u>	<u>12"</u>
Bearing <u>S 34 1/2 E</u>	<u>N 58 E</u>
Distance <u>42 LKS</u>	<u>7 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1958 By Pete Meyer
Location filed _____
Monument Found both original BT's. set 2' x 5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Bearing Trees, Reference Objects

Species <u>Red Pine</u>	<u>Red Pine</u>	<u>Jack Pine</u>
Diameter <u>11"</u>	<u>13"</u>	<u>9"</u>
Bearing <u>S 61 W</u>	<u>S 5 W</u>	<u>N 55 W</u>
Distance <u>34.5'</u>	<u>70.6'</u>	<u>10.9'</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER, 1958

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____