

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. E19

CASS COUNTY LAND CORNER RECORD

T. 145 R. 27 M. 574 Coordinates: X _____ Y _____
N 1/4 11 Corner common to sections 2, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>Tam</u>	<u>Tam</u>
Diameter <u>4"</u>	<u>3"</u>
Bearing <u>N 60W</u>	<u>S 40W</u>
Distance <u>70 LBS</u>	<u>38 LBS</u>

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1958 By Pete Meyer
Location filed _____
Monument Set 2" x 5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species <u>Tamarack</u>	<u>B. Spruce</u>	<u>B. Spruce</u>
Diameter <u>5"</u>	<u>6"</u>	<u>5"</u>
Bearing <u>S 40 1/2 E</u>	<u>S 68 W</u>	<u>N 11 1/2 W</u>
Distance <u>33.2'</u>	<u>33.7'</u>	<u>50.3'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PETE MEYER - CERTIFICATE - 1958

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____