

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration


Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. E5

CASS COUNTY LAND CORNER RECORD



T. 145 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 7 Corner common to sections 5, 6, 7, 8

EXISTING SURVEYS

* Original Government Survey

Year surveyed 1873
 Original monument Post
in edge of swamp

Bearing Trees

Species	<u>N. pine</u>	<u>N. pine</u>	<u>N. pine</u>	<u>N. pine</u>
Diameter	<u>28"</u>	<u>24"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>N29E</u>	<u>S79W</u>	<u>N71W</u>	<u>N77E</u>
Distance	<u>14LKS</u>	<u>50LKS</u>	<u>90LKS</u>	<u>39LKS</u>

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1963 By PETE MEYER
 Location filed _____
 Monument Set 2" x 5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Bearing Trees, Reference Objects

Species	<u>B. Pine</u>	<u>B. Pine</u>	<u>Cedar</u>	<u>B. Pine</u>
Diameter	<u>15"</u>	<u>11"</u>	<u>4"</u>	<u>6"</u>
Bearing	<u>N73E</u>	<u>S74 1/2 E</u>	<u>S38 1/2 W</u>	<u>N28W</u>
Distance	<u>21.2'</u>	<u>72.4'</u>	<u>29.5'</u>	<u>62.9'</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By CERTIFICATE - PETE MEYER - 1963

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____