


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. J17

CASS COUNTY LAND CORNER RECORD

T. 145 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 15 Corner common to sections 10, 11, 14, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Species	Bearing Trees			
	<u>Balsam</u>	<u>N. Pine</u>	<u>Birch</u>	<u>Birch</u>
Diameter	<u>4"</u>	<u>8"</u>	<u>8"</u>	<u>8"</u>
Bearing	<u>N64E</u>	<u>S47 1/2 E</u>	<u>N30W</u>	<u>S55W</u>
Distance	<u>25LKS</u>	<u>35LKS</u>	<u>12LKS</u>	<u>98LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1958 By PETE MEYER
Location filed _____
Monument Set 2" x 5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing Trees, Reference Objects		
	<u>B. Pine</u>	<u>Tamarack</u>	<u>Birch</u>
Diameter	<u>21"</u>	<u>9"</u>	<u>6"</u>
Bearing	<u>N51W</u>	<u>S34W</u>	<u>N50E</u>
Distance	<u>52.1'</u>	<u>61.3'</u>	<u>31.2'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By CERTIFICATE - PETE MEYER - 1958

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____