


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. J 5

CASS COUNTY LAND CORNER RECORD

T. 145 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 18 Corner common to sections 7, 8, 17, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Species	Bearing	Trees	
<u>Tam</u>	<u>Tam</u>	<u>Cedar</u>	<u>Cedar</u>
<u>5"</u>	<u>5"</u>	<u>4"</u>	<u>6"</u>
<u>S11 E</u>	<u>N70 W</u>	<u>S21 1/2 W</u>	<u>N12 E</u>
<u>15 LKS</u>	<u>33 LKS</u>	<u>30 LKS</u>	<u>40 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1900 ± By CDE
Location filed USFS
Monument LAKE WINNIE RESERVOIR MAP
INDICATES MON. FOUND

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____