


Index No. L 21

CASS COUNTY LAND CORNER RECORD

T. 145 R. 27 M. 5TH Coordinates: X _____ Y _____
E 1/4 14 Corner common to sections 13, 14



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

| | | | | |
|----------|---------------|---------------|-------|-------|
| | Bearing Trees | | | |
| Species | <u>Tam</u> | <u>Tam</u> | _____ | _____ |
| Diameter | <u>3"</u> | <u>5"</u> | _____ | _____ |
| Bearing | <u>N10W</u> | <u>N15W</u> | _____ | _____ |
| Distance | <u>36 LKS</u> | <u>50 LKS</u> | _____ | _____ |

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

| | | | | |
|----------|-------|-------|-------|-------|
| Species | _____ | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Bearing Trees, Reference Objects

| | | | | |
|----------|-------|-------|-------|-------|
| Species | _____ | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | | | |
|-------|-------|-------|-------|-------|
| _____ | _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____