Index No. CASS COUNTY I	LAND CORNER RECORD
T R M Coordinates: X	
Corner common to sections	
	ISTING SURVEYS
Original Government Survey	Original Evidence Found
Year surveyed	Year of search by
Original monument	
	= Corner
Bearing Trees	Original Bearing Trees Found
Species	Species
Diameter	Diameter
Bearing	Bearing
Distance	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed By	Year of search By
Location filed:	Location filed:
Monument:	Monument:
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species	Species
Diameter	Diameter
Bearing	Bearing
Distance	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed By Location filed:	Year of search By Location filed:
Monument:	Monument:
Certificate of Location of Government Corner filed in Cass County	Ву
Recorders Office as Document	Date

Index No. NZ/ CASS COUNTY LANI	CORNER RECORD
+ 145 - 27 × 574 Constitution V	
T. <u>145</u> R. <u>27</u> M. <u>574</u> Coordinates: X <u>NE 23</u> Corner common to sections <u>17, 14, 23, 2</u>	77
	SURVEYS
Original Government Survey	Original Evidence Found
Year surveyed 1873	Year of searchBy
Original monument Post	Monument found
Species Poplar Poplar Poplar Poplar	Original Bearing Trees Found O = Corner Species
	Diameter
Bearing SYOE S57W N39W N49E Distance BLKS IBLKS 244KS 304KS	Bearing
Distance 8 LKS 18 LKS 24 LKS 30 LKS	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed By	Year of search By
Location filed	
Monument	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species	
Diameter	
Distance	
	· · · · ·
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed By	Year of search By
Location filed	
Monument	
· · · · · · · · · · · · · · · · · · ·	
	-
Remonumentation certificate prepared	By