

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. R9

CASS COUNTY LAND CORNER RECORD

T. 145 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 29 Corner common to sections 20, 21, 28, 29



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1873  
Original monument 12" Spruce

Bearing Trees			
Species	Bearing	Tree	Distance
<u>Spruce</u>	<u>6"</u>	<u>Cedar</u>	<u>4"</u>
<u>Spruce</u>	<u>8"</u>	<u>Cedar</u>	<u>4"</u>
<u>38LKS</u>	<u>26LKS</u>	<u>40LKS</u>	<u>18LKS</u>

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1958 By Pete Meyer  
Location filed \_\_\_\_\_  
Monument Set 2" x 5" galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
<u>Birch</u>	<u>8"</u>	<u>N 27 W</u>	<u>25.4'</u>
<u>W Spruce</u>	<u>10"</u>	<u>S 33 W</u>	<u>29.0'</u>
<u>Balsam</u>	<u>10"</u>	<u>S 21 1/2 E</u>	<u>30.1'</u>
<u>Cedar</u>	<u>9"</u>	<u>S 8 1/2 E</u>	<u>34.3'</u>

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By CERTIFICATE - PETE MEYER - 1958

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_