

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_


= Corner

**EXISTING SURVEYS**

Original Government Survey

Original Evidence Found

Year surveyed \_\_\_\_\_

Year of search \_\_\_\_\_ by \_\_\_\_\_

Original monument \_\_\_\_\_

Monument found \_\_\_\_\_

Bearing Trees

Original Bearing Trees Found

Species \_\_\_\_\_

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed:

Location filed:

Monument:

Monument:

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed:

Location filed:

Monument:

Monument:

Certificate of Location of Government Corner filed in Cass County

By \_\_\_\_\_


Recorders Office as Document \_\_\_\_\_

Date \_\_\_\_\_

Index No. N3

CASS COUNTY LAND CORNER RECORD

T. 145 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1419 Corner common to sections 18,19



EXISTING SURVEYS

Original Government Survey	
Year surveyed <u>1873</u>	
Original monument <u>bst</u>	
Bearing Trees	
Species <u>J. Pine</u>	_____
Diameter <u>12"</u>	_____
Bearing <u>N67E</u>	_____
Distance <u>34Lks</u>	_____

Original Evidence Found	
Year of search _____	By _____
Monument found _____	
Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

O = Corner

Subsequent Corner Restoration		
Year surveyed <u>1986</u>	By <u>Walt Curo</u>	
Location filed <u>Corner Certificate - Doc # 291631</u>		
Monument <u>set 2x60" 1/2" w/ marked brass cap at post position</u>		
Bearing Trees, Reference Objects		
Species <u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
Diameter <u>8"</u>	<u>6"</u>	<u>5"</u>
Bearing <u>N50°W</u>	<u>S70°E</u>	<u>S30°W</u>
Distance <u>18.38'</u>	<u>5.11'</u>	<u>14.80'</u>

Evidence of Subsequent Corner Restoration	
Year of search _____	By _____
_____	
_____	
Bearing Trees, Reference Objects	
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration	
Year surveyed _____	By _____
Location filed _____	
Monument _____	
_____	
_____	
_____	
_____	
_____	
_____	
_____	
_____	
_____	
_____	
_____	
_____	

Evidence of Subsequent Corner Restoration Found	
Year of search _____	By _____
<u>Certificate - Walt Curo - 1986</u>	
_____	
_____	
_____	
_____	
_____	
_____	
_____	
_____	
_____	
_____	
_____	