


Index No. P13

CASS COUNTY LAND CORNER RECORD

T. 145 R. 28 M. 5TH Coordinates: X _____ Y _____
E 1/4 R1 Corner common to sections 21, 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

| | | |
|----------|------------------|---------------|
| | Bearing Trees | |
| Species | <u>Tam</u> | <u>Tam</u> |
| Diameter | <u>3"</u> | <u>3"</u> |
| Bearing | <u>S17 1/2 W</u> | <u>N49 E</u> |
| Distance | <u>106 LKs</u> | <u>38 LKs</u> |

Original Bearing Trees Found

| | | |
|----------|-------|-------|
| Species | _____ | _____ |
| Diameter | _____ | _____ |
| Bearing | _____ | _____ |
| Distance | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | |
|----------|-------|-------|
| Species | _____ | _____ |
| Diameter | _____ | _____ |
| Bearing | _____ | _____ |
| Distance | _____ | _____ |

Bearing Trees, Reference Objects

| | | |
|-------|-------|-------|
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____