


Index No. T 17

CASS COUNTY LAND CORNER RECORD

T. 145 R. 28 M. 5th Coordinates: X _____ Y _____
E 1/4 R 7 Corner common to sections 26, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument BST

	Bearing	Trees
Species	<u>N. Pine</u>	<u>N. Pine</u>
Diameter	<u>14"</u>	<u>12"</u>
Bearing	<u>N36W</u>	<u>N57E</u>
Distance	<u>70 LKS</u>	<u>64 LKS</u>

Original Evidence Found

Year of search 1904 By CDE
Monument found RESENDER MAP
SHOWS CORNER FOUND

	Bearing	Trees
Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1939 By DNR-Engineering
Location filed map on file
Monument, Survey by G. Amidon 1939 - 2 B.T.S
at 1/4 corner. N 1/2 15 iron pipe

Evidence of Subsequent Corner Restoration

Year of search 1936 By J.A. GUELHANG
1" x 12" IRON BOLT SET ACCORDING TO THE
RECORD PLAT OF BENA

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Bearing Trees, Reference Objects

<u>W. PINE</u>	<u>W. PINE</u>	_____
<u>10"</u>	<u>10"</u>	_____
<u>S 31° W</u>	<u>S 7° E</u>	_____
<u>94 1/2 lks</u>	<u>109 lks</u>	_____

Subsequent Corner Restoration T 17

Year surveyed _____ By _____
Location filed _____
Monument Dec. 2004 T. Freeman #21367
Cert. of Survey shows iron monument
Set by license no 21367

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - BENA HARRY USHER 1903

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____