


Index No. V13

CASS COUNTY LAND CORNER RECORD

T. 145 R. 28 M. 5th Coordinates: X _____ Y _____
NE 33 Corner common to sections 27, 28, 33, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>J Pine</u>	<u>J Pine</u>	<u>Ash</u>	<u>Tan</u>
<u>12"</u>	<u>10"</u>	<u>6"</u>	<u>4"</u>
<u>N12W</u>	<u>S30W</u>	<u>S45E</u>	<u>N72E</u>
<u>62 LKS</u>	<u>70 LKS</u>	<u>90 LKS</u>	<u>81 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By C. J. Bark
Location filed Co Hwy Dept. Book # 147 in Box "Field Book"
Monument wood post of 5768' from west 6' S. of line. PAGE 3

Evidence of Subsequent Corner Restoration

Year of search SEP 1936 By J. A. GIELHARD

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>ORIG J Pine</u>	<u>10"</u>	<u>S50°W</u>	<u>32 LKS</u>
<u>ELM</u>	<u>10"</u>	<u>N38°15'W</u>	<u>91 LKS</u>
<u>CEDAR</u>	<u>10"</u>	<u>S12°E</u>	<u>68 1/4 LKS</u>
		<u>DEAD</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
FEB 2002
CERT of SVY SHOWS MON FOUND
Aug 2002 B L. Luelling
CERT of SVY shows mon found.

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____