

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. 213

CASS COUNTY LAND CORNER RECORD

T. 145 R. 28 M. 5TH Coordinates: X _____ Y _____
SE 33 Corner common to sections 33, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

	Bearing	Trees	Distance
Species	<u>Y. Pine</u>	<u>Y. Pine</u>	
Diameter	<u>9"</u>	<u>10"</u>	
Bearing	<u>N23E</u>	<u>N40W</u>	
Distance	<u>36 LKS</u>	<u>12 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

	Bearing	Trees	Distance
Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1907 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK 8 P. 37-38
Monument FRASER GOVT 9" Y. PINE N23E 36 LKS.
10" Y. PINE N40W 12 LKS.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

	Bearing	Trees	Distance
Species			
Diameter			
Bearing			
Distance			

Bearing Trees, Reference Objects

	Bearing	Trees	Distance
Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____