Index No. N 15

# CASS COUNTY LAND CORNER RECORD

T. 145 R. 29 M. 5TH Coordinates: X _____ Y _____
N 1/4 22 Corner common to sections 15, 22




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1874
Original monument Post

Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | Bl. Pine | Bl. Pine | | |
| Diameter | 8" | 8" | | |
| Bearing | S19E | N25E | | |
| Distance | 29 LKS | 19 LKS | | |

### Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____