


Index No. N5

CASS COUNTY LAND CORNER RECORD

T. 145 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 19 Corner common to sections 17, 18, 19, 20



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1874
 Original monument Post

Species	Bearing	Tree	Distance
<u>Y. Pine</u>	<u>Y. Pine</u>	<u>Y. Pine</u>	<u>Y. Pine</u>
<u>16"</u>	<u>14"</u>	<u>10"</u>	<u>6"</u>
<u>N14E</u>	<u>N50W</u>	<u>S28E</u>	<u>S60W</u>
<u>20LKS</u>	<u>20LKS</u>	<u>18LKS</u>	<u>16LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1958 By Pete Meyer
 Location filed _____
 Monument Set 6" x 5" cylindrical concrete monument with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>J. Pine</u>	<u>13"</u>	<u>N49W</u>	<u>45.6'</u>
<u>J. Pine</u>	<u>12"</u>	<u>S43 1/2 W</u>	<u>28.4'</u>
<u>J. Pine</u>	<u>10"</u>	<u>S15E</u>	<u>37.7'</u>
<u>J. Pine</u>	<u>12"</u>	<u>S80E</u>	<u>42.0'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1958

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____