


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. P 25

CASS COUNTY LAND CORNER RECORD

T. 145 R. 29 M. 5TH Coordinates: X _____ Y _____
E11424 Corner common to sections 24 AND 19-145-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument bst

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Jil. Pine Nil. Pine _____
Diameter 7" 24" _____
Bearing N13 1/2 E S74W _____
Distance 24 LKS 73 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1968 By USFS
Location filed _____
Monument Set corner proportionally between
NE & SE Corners Section 24 1/2 mile 2992.92'
set 2x60" 1/2" w/ 3" bronze cap

Evidence of Subsequent Corner Restoration

Year of search 1979 By DNR-Engineering
map & notes in file
Found 2" 1/2" w/ 3" Cap RLS 6807
1968
also old E-W fence 335' S

Bearing Trees, Reference Objects

Species Jil. Pine Jil. Pine Nil. Pine
Diameter 12" 11" 9"
Bearing N8E N88W S17E
Distance 45.53' 66.08' 92.87'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1986 By Walt Curo
Location filed Corner Certificate - Doc # 291633
Monument Find cast iron monument set by Dave
Claypool, and set a 2x60" 1/2" w/ brass
cap in its place
9" Aspen N85°E 89.62'
8" Jack Pine S58°E 165.54'
7" Burroak S50°E 123.09'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - DAVE CLAYPOOL - 1981
Certificate - Walt Curo - 1986

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____