


Index No. S-T 21

CASS COUNTY LAND CORNER RECORD

T. 145 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 2 Corner common to sections 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Bearing Trees	
Species <u>Spruce</u>	<u>W. oak</u>
Diameter <u>6"</u>	<u>8"</u>
Bearing <u>N33W</u>	<u>N18E</u>
Distance <u>31 Lks</u>	<u>35 Lks</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1974 By BLM  
 Location filed Sec. of State  
 Monument Set 2 1/2 x 30" l.p. willow sap WC  
T145N, R29W  
S26 S25  
MC  
1974

Bearing Trees, Reference Objects

Species <u>Elm</u>	<u>W. Birch</u>
Diameter <u>12"</u>	<u>7"</u>
Bearing <u>N66E</u>	<u>S87W</u>
Distance <u>65 Lks</u>	<u>55 Lks</u>

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_