


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____

Year of search _____ by _____

Original monument _____

Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____


Certificate of Location of Government Corner filed in Cass County

By _____

Recorders Office as Document _____

Date _____

T. 145 R. 29 M. 5TH Coordinates: X _____ Y _____
SE 34 Corner common to sections 34, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Bearing Trees

Species	<u>Bl. oak</u>	<u>Bl. Ash</u>		
Diameter	<u>9"</u>	<u>10"</u>		
Bearing	<u>N10E</u>	<u>NSW</u>		
Distance	<u>44KS</u>	<u>127 LKS</u>		

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1926 By GLO
Location filed Sec. of State
Monument End of the orig. B.T.s (Stumps) Set 2x36"
1 1/2" w brass cap.

Evidence of Subsequent Corner Restoration

Year of search 1969 By William Okerman
Found GLO monument in good condition.

(Corner at P.I. of blazed lines E-w i N) 7145N/R29W
534/535

Bearing Trees, Reference Objects 1926

Species	<u>Balsam</u>	<u>Birch</u>		
Diameter	<u>6"</u>	<u>8"</u>		
Bearing	<u>N9-30W</u>	<u>N27-45E</u>		
Distance	<u>78 LKS</u>	<u>37 LKS</u>		

Bearing Trees, Reference Objects

Ash	<u>W. PINE</u>	<u>Elm</u>	<u>P. Oak</u>
<u>8"</u>	<u>12"</u>	<u>6"</u>	<u>4"</u>
<u>N167W</u>	<u>NSW</u>	<u>N21E</u>	<u>N57E</u>
<u>23.48'</u>	<u>46.00'</u>	<u>27.17'</u>	<u>33.43'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1969