


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____

NE 16 Corner common to sections 9, 10, 15, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search 1933 by Bandy
Monument found _____

Notes page 64

Bearing Trees

Species	Yellow Pine	Black Pine	Yellow Pine	Yellow Pine
Diameter	30"	6"	30"	24"
Bearing	N 48° W	S 38° E	S 34° W	N 45° W
Distance	27 links	130 links	11 links	58 links

Original Bearing Trees Found

Species	N. Pine stump		
Diameter	30"		
Bearing	N 45° W		
Distance	58 links		

Subsequent Corner Restoration

Year surveyed 12/1929 By A.W. Prudlo, Asst. Engr.
Location filed: Ditch Shelf 1, Book 167, page 3
Monument:
S.R. #10 Transit notes, indicates sec line PI at station 38+02.5 and reference points as follows.

Evidence of Subsequent Corner Restoration

Year of search 7/1933 By W.W. Bandy, Surveyor, GLO
Location filed: MN Historical Society, Notes pg 64 T145 N R30W
Monument: Set 6" conc cylinder with brass tablet S 9 | S 10
from remains of original witness tree, up 6", in S 16 | S 15
center of Black Duck Road and witnessed as 1933
follow.

Bearing Trees, Reference Objects

Species	Pop.	Pop.		
Diameter	3"	3"		
Bearing	NE	SE		
Distance	40.4'	30.4'		

Bearing Trees, Reference Objects

Species	Jack Pine	White Pine	Burr Oak	Burr Oak
Diameter	6"	5"	20"	4"
Bearing	N 86 1/4° E	S 71 1/2° E	S 46 1/4° W	N 65 3/4° W
Distance	92 links	80 links	63 links	67 links

Subsequent Corner Restoration

Year surveyed 4/1980 By M. Hayes, LS 20774
Location filed: USFS Book 2, page 48
Monument: Found corner
2' W. of centerline of Blackduck Hwy. and witnessed.
24" White Oak, S 46° W, 41.6'(1933)
Jack Pine stump, N 86° E, 60.7'(1933)
White Pine stump, S 71° E, 52.8'(1933)
4" Cedar Post, West, 46.1' FSLP

Evidence of Subsequent Corner Restoration Found


Year of search _____ By _____
Location filed: _____
Monument: _____

2/2001, CCHD/SO
#2001.002
Found PK nail, 4' W. of centerline Co. Rd. #10 and witnessed.
White Oak stump, S 46° W, 41.6'(1933)
13" Spruce, N 30° E, 81.22' 16d duplex nail
10" Spruce, S 60° E, 49.54' 16d duplex nail
10" Spruce, S 30° W, 78.56' 16d duplex nail
10" Spruce, N 78° W, 46.18' 16d duplex nail

Index No. J 13

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5th Coordinates: X _____ Y _____
NE 16 Corner common to sections 9, 10, 15, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1879
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Tree	Species	Bearing	Tree
<u>Y. Pine</u>	<u>30"</u>	<u>Bl. oak</u>	<u>Y. Pine</u>	<u>30"</u>	<u>Y. Pine</u>
<u>30"</u>	<u>N 48 W</u>	<u>6"</u>	<u>30"</u>	<u>534 W</u>	<u>24"</u>
<u>27 LKS</u>	<u>130 LKS</u>	<u>11 LKS</u>	<u>50 LKS</u>	<u>11 LKS</u>	<u>50 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1933 By GLO
Location filed Sec. of state
Monument Find NW BIT stump set concrete man
24" lang 6" Dia willow cap T 145 N R 30 W
Cor. in center of Blackduck RD S 9 / S 10
516 / 515

Evidence of Subsequent Corner Restoration

Year of search 4/1980 By USFS
Found monument 2' W. of & CR #10

Species	Bearing	Tree	Reference Objects	Species	Bearing	Tree	Reference Objects
<u>J. Pine</u>	<u>6"</u>	<u>Willow</u>	<u>1933</u>	<u>GLO Oak</u>	<u>24"</u>	<u>GLO J. Pine</u>	<u>GLO W. Pine</u>
<u>6"</u>	<u>N 86 1/4 E</u>	<u>5"</u>	<u>20"</u>	<u>24"</u>	<u>5 46 W</u>	<u>Stp</u>	<u>Stp</u>
<u>92 LKS</u>	<u>80 LKS</u>	<u>63 LKS</u>	<u>67 LKS</u>	<u>41.6'</u>	<u>60.7'</u>	<u>52.8'</u>	<u>57 1/2 E</u>

Species	Bearing	Tree	Reference Objects
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

J 13

Subsequent Corner Restoration

Year surveyed 2/2001 By CCSO
Location filed CCSO
Monument Found PK nail 4' W. of &
CR #10 at bearing and distance
from stump which Mike Hayes says
is remains of GLO Oak. Add
witnesses as follows

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

- 13" Spruce N 30° E, 81.22*
- 10" Spruce S 60° E, 49.54*
- 10" Spruce S 30° W, 78.56*
- 10" Spruce N 78° W, 46.18*
- *distance to double head nail

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____