Index No. A23

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5th Coordinates: X _____ Y _____

N1141 Corner common to sections 1 AND 36-146-30



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Jiline	Jiline		
Diameter	10"	10"		
Bearing	S76W	N65W		
Distance	66LKS	79LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1933 By GLO

Location filed Sec. of state

Monument Found remains of both B.T.S - Set 1x36" Jiline brass cap 1/4 S36 S1 1933

Bearing Trees, Reference Objects

Species	Jiline	Black		
Diameter	9"	12"		
Bearing	S2E	N43W		
Distance	97LKS	88LKS		

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____