


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____

MC #28 Corner common to sections 1 and 6-145-29



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search 1900 by COE
Monument found _____

Lake Winnibigoshish Map

Bearing Trees

Species	<u>N. Pine</u>	<u>J. Pine</u>	_____
Diameter	<u>18"</u>	<u>6"</u>	_____
Bearing	<u>N 48° W</u>	<u>S 89° E</u>	_____
Distance	<u>32 links</u>	<u>68 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1900 By T.M. Fowble, COE
Location filed: Lake Winnibigoshish Reservoirs Map
Monument:
Indicates original corner recovered.

Evidence of Subsequent Corner Restoration

Year of search 6/1933 By W.W. Bandy, Surveyor
Location filed: Resurvey Notes T145N
Monument: Set 6" concrete cylinder w/ brass tablet R30W | R29W
from remains of GLO witnesses. S 1 | S 6
MC
1933

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>Norway Pine</u>	<u>Jack Pine</u>	<u>Norway Pine</u>	<u>Norway Pine</u>
Diameter	<u>20"(GLO)</u>	<u>stump(GLO)</u>	<u>9"</u>	<u>9"</u>
Bearing	<u>N 48° W</u>	<u>S 87° E</u>	<u>S 19 1/2° E</u>	<u>N 32 1/4° W</u>
Distance	<u>32 links</u>	<u>68 links</u>	<u>7 links</u>	<u>44 links</u>

Subsequent Corner Restoration

Year surveyed 8/1962 By R.H. McDonald, USFS
Location filed: USFS Book 1, page 18
Monument: Found corner
notes witnesses.
18" Red Pine, N 48° W, 21.12' (GLO)
9" N. Pine, S 29°30' E, 4.62' (1933)
N. Pine, N 30° W, 29.04' (1933)
Steel Sign Post, North, 3.2'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

