


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____
E 1/4 11 Corner common to sections 11, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Blk. Pine</u>	<u>Blk. Pine</u>	_____
Diameter	<u>2.5"</u>	<u>3"</u>	_____
Bearing	<u>S 30° W</u>	<u>S 58° E</u>	_____
Distance	<u>100 links</u>	<u>13 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed Cir 1930 By CCC
Location filed: Form 874
Monument: No stake
22" norway tree faced on S scribed 1/4 S BT, this tree sets in small green jack pine.

Evidence of Subsequent Corner Restoration

Year of search 6/1933 By W.W. Bandy, Surveyor
Location filed: Resurvey Notes 1/4
Monument: Set 1"x 3' iron post with brass cap S 11 | S 12
At proportionate position. 1933

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>Norway Pine</u>	<u>Jack Pine</u>	_____
Diameter	<u>12"</u>	<u>9"</u>	_____
Bearing	<u>N 41 1/2° E</u>	<u>N 28° W</u>	_____
Distance	<u>181 links</u>	<u>113 links</u>	_____

Subsequent Corner Restoration

Year surveyed 5/1966 By J. Ekstrom, USFS
Location filed: USFS Book 1, page 59
Monument: Found GLO iron with brass cap and witnesses.
Steel Sign Post, East, 4.6'
17" N. Pine, N 41° E, 119.46' (1933)
9" N. Pine, N 3° W, 40.2'
9" J. Pine, N 60° E, 35.7'


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. G 21

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 11 Corner common to sections 11, 12



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Bl. Pine Bl. Pine _____
Diameter 2 1/2" 3" _____
Bearing N 30W 55BE _____
Distance 100 LKS 13 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1933 by GLO
Location filed Sec. of State
Monument Set 1x36" 1/4" brass cap
1/4
5 11/512
1933

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species N. Pine J. Pine _____
Diameter 12" 9" _____
Bearing N 41 1/4 E N 20W _____
Distance 181 LKS 113 LKS _____

Bearing Trees, Reference Objects

Red Pine Jack Pine _____
9" 9" _____
N 3W N 60E _____
40.2' 35.7' _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1966

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____