


Index No. J.0-02.5

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

MC #22 Corner common to sections 7, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Original Evidence Found

Year of search 1900 by COE  
Monument found \_\_\_\_\_

Lake Winnibigoshish Map

Bearing Trees

Species	<u>White Oak</u>	<u>White Pine</u>	_____
Diameter	<u>12"</u>	<u>24"</u>	_____
Bearing	<u>N 71° E</u>	<u>S 10° E</u>	_____
Distance	<u>48 links</u>	<u>54 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1900 By T.M. Fowble, COE  
Location filed: Lake Winnibigoshish Reservoirs Map  
Monument:  
Indicates original corner recovered.

Evidence of Subsequent Corner Restoration

Year of search 8/1933 By W.W. Bandy, Surveyor, GLO  
Location filed: MN Historical Society, notes page 87 WC  
Monument: Set 6" concrete cylinder w/ brass cap from remains of GLO witness, 0.63 chains(41.58') E. of original corner position, on the W. shore of a point of land and witnessed as follows. MC  $\frac{T145N}{S7}$  /  $\frac{S18}{R30W}$  1933

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>W. Pine stump</u>	<u>Burr Oak</u>	<u>Burr Oak</u>
Diameter	<u>30"(GLO)</u>	<u>12"</u>	<u>6"</u>
Bearing	<u>S 10° E</u>	<u>N 32 1/2° E</u>	<u>S 4 1/2° W</u>
Distance	<u>54 links</u>	<u>81 links</u>	<u>19 links</u>

Subsequent Corner Restoration

Year surveyed 1/1934 By J.A. Gjelhaug, Engineer, CCC  
Location filed: USFS Form 874-9  
Monument: Brass capped cement up 5", and witnesses as follows.  
8" White Oak, N 31° E, 81 links  
4" White Oak, S 3° W, 19 1/2 links

Evidence of Subsequent Corner Restoration Found


Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

5/1996, C. Krause, USFS  
USFS Book 2, page 44  
chained from N 1/4 sec. 18. Position for WCMC now falls 200'+/- out in water.

Index No. J 2-3

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
ML# 22 Corner common to sections 7, 18



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1874  
Original monument Post

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species W. oak W. Pine  
Diameter 12" 24"  
Bearing N71E S10E  
Distance 4 BLKS 54 LKS

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1933 By GLO  
Location filed Sec of State  
Monument Find stump of SE BIT - cor on lake set w/c  
MC Concrete mon 24" long 5" dia w/ brass cap  
cor is 0.63 CH E. of true point w/c

Evidence of Subsequent Corner Restoration  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
Species Pr. oak Br. oak  
Diameter 12" 6"  
Bearing N32 1/2 E S41 1/2 W  
Distance 81 LKS 19 LKS

Bearing Trees, Reference Objects  
\_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_