


Index No. L 17

CASS COUNTY LAND CORNER RECORD

T. 14S R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 15 Corner common to sections 14, 15



○ = Corner

EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1874  
 Original monument lost

Species	Bearing	Trees
<u>W. Pine</u>	<u>Aspen</u>	
<u>40"</u>	<u>6"</u>	
<u>N 38 E</u>	<u>S 88 W</u>	
<u>9 LKS</u>	<u>34 LKS</u>	

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance

**Subsequent Corner Restoration**  
 Year surveyed 1933 By GLO  
 Location filed SEC. OF STATE  
 Monument Found remains of both BITs Set 1x36"  
1. P. w/ brass cap  
14  
515/514  
1933

**Evidence of Subsequent Corner Restoration**  
 Year of search 1963 By PETE MEYER  
 Found GLO monument in good condition.

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
<u>Pv. oak</u>	<u>6"</u>	<u>S 86 1/4 E</u>	<u>42 LKS</u>
<u>Br oak</u>	<u>6"</u>	<u>N 45 1/4 W</u>	<u>21 LKS</u>

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
<u>OAK</u>	<u>12"</u>	<u>S 19 W</u>	<u>23.0'</u>
<u>OAK</u>	<u>12"</u>	<u>N 45 1/2 W</u>	<u>13.86'</u>
<u>OAK</u>	<u>10"</u>	<u>N 86 1/4 E</u>	<u>27.72'</u>

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_