Index No. L 9

# CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____

E 1/4 17 Corner common to sections 16,17




## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1874

Original monument Post

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | Ironwood | Aspen | | |
| Diameter | 5" | 10" | | |
| Bearing | N60W | S65E | | |
| Distance | 13 LKS | 30 LKS | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1933 By GLO

Location filed Sec. of State

Monument Set 2x36" I.P. w/brass cap 1/4 S17/S16 1933

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | Poplar | Poplar | | |
| Diameter | 6" | 8" | | |
| Bearing | S76E | N80 1/4 W | | |
| Distance | 36 LKS | 30 LKS | | |

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____