


Index No. M 23

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
C.S. 116 Corner common to sections 13



EXISTING SURVEYS

Original Government Survey

Year surveyed 1933
Original monument 1x 36" l.p. willow cap 1933

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Tam Tam
Diameter 4" 4"
Bearing N27E N47W
Distance 4 LKS 20 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1966 By William Okerman
Location filed _____
Monument Found 6" monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Tamarack Tamarack
Diameter 6" 6"
Bearing N43W S81E
Distance 9.5' 7.8'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1966

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____