


Index No. N13

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 574 Coordinates: X _____ Y _____
NE 21 Corner common to sections 15, 16, 21, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1879
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>white</u>	<u>white</u>	<u>white</u>
Diameter	<u>30"</u>	<u>30"</u>	<u>24"</u>
Bearing	<u>N48W</u>	<u>S10E</u>	<u>S45W</u>
Distance	<u>64LKS</u>	<u>70LKS</u>	<u>80LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1933 By GLO
Location filed SEC of State
Monument End remains of SE & SW BT'S set
concrete mon 24" long 6" dia w/ brass cap T145N R30W

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman
Found GLO monument in good condition.

516 | 515
521 | 522
1933

Bearing Trees, Reference Objects

Species	<u>Br oak</u>	<u>oak</u>	<u>Br oak</u>	<u>Br oak</u>
Diameter	<u>8"</u>	<u>14"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>N51 1/4 E</u>	<u>S71 1/4 E</u>	<u>S147 1/4 W</u>	<u>N32 W</u>
Distance	<u>99 LKS</u>	<u>76 LKS</u>	<u>113 LKS</u>	<u>102 LKS</u>

Bearing Trees, Reference Objects

Red Oak	<u>Oak</u>	<u>Burr Oak</u>	<u>Burr Oak</u>
Diameter	<u>6"</u>	<u>9"</u>	<u>9"</u>
Bearing	<u>S71 E</u>	<u>N32 W</u>	<u>S11 W</u>
Distance	<u>50.2'</u>	<u>67.3'</u>	<u>54.0'</u>
	<u>(GLO BT)</u>	<u>(GLO BT)</u>	<u>27.85'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
(CERTIFICATE - BILL OKERMAN - 1966)

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____