


Index No. 0 19

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
C.N. 116 Corner common to sections 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1933
Original monument 1 x 36" / 1 P. W / brass N 116° 52' 30" W
cup 1933

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Poplar Poplar
Diameter 4" 5"
Bearing S 60 1/2° E N 84° W
Distance 20 LKS 8 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1966 By William Okerman
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species W. Spruce Elm
Diameter 6" 8"
Bearing S 89° W S 34° E
Distance 38.8' 57.95'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1966

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____